

## UNIVERSITI TEKNOLOGI MALAYSIA

## DECLARATION OF THESIS / UNDERGRADUATE PROJECT PAPER AND COPYRIGHT

Author's full name : AHMAD SAYUFEI BIN ZAINUDDINDate of birth : 5 FEBRUARY 1970Title : MAINTENANCE CONSIDERATION IN SLOPE DESIGNAcademic Session: 2008/2009 - 1

I declare that this thesis is classified as :

**CONFIDENTIAL**

(Contains confidential information under the Official Secret Act 1972)\*

**RESTRICTED**

(Contains restricted information as specified by the organization where research was done)\*

**OPEN ACCESS**

I agree that my thesis to be published as online open access (full text)

I acknowledged that Universiti Teknologi Malaysia reserves the right as follows:

1. The thesis is the property of Universiti Teknologi Malaysia.
2. The Library of Universiti Teknologi Malaysia has the right to make copies for the purpose of research only.
3. The Library has the right to make copies of the thesis for academic exchange.




SIGNATURE

700205-10-5015

(NEW IC NO. /PASSPORT NO.)

Date : 24 November 2008

Certified by :



SIGNATURE OF SUPERVISOR

Prof. Dr. Muhd. Zaimi Abd Majid

NAME OF SUPERVISOR

Date : 24 November 2008


**NOTES :** \* If the thesis is CONFIDENTIAL or RESTRICTED, please attach with the letter from the organization with period and reasons for confidentiality or restriction.

**"I/We\* hereby declare that I/we\* have read this thesis and in my/our\*  
opinion this thesis is sufficient in terms of scope and quality for  
the award of the degree of Master of Civil Engineering (Construction Management)"**

**Signature**

**:**

.....



**Name of Supervisor**

**:**

**PROF. DR MUHD. ZAIMI ABD MAJID**

**Date**

**:**

**24 NOVEMBER 2008**

---

**MAINTENANCE CONSIDERATION IN SLOPE DESIGN**

**AHMAD SAYUFEI BIN ZAINUDDIN**

A project report submitted in partial fulfillment of the  
requirements for the award of the degree of  
Master of Civil Engineering (Construction Management)

Faculty of Civil Engineering  
Universiti Teknologi Malaysia

NOVEMBER 2008

I declare that this thesis entitled "*Maintenance Consideration in Slope Design – Case Study*" is the result of my own research except as cited in the references. The thesis has not been accepted for any degree and is not concurrently submitted in candidature of any other degree.

Signature

:



Name

:

**AHMAD SAYUFEI BIN ZAINUDDIN**

Date

:

**24 NOVEMBER 2008**

*Dedicated to my beloved mother, families and friends;*

*Fatmah Bt Hashim*

*Augastinar Mohd Arif*

*Ahmad Rohaizad*

*Rohaizah*

*Ahmad Rohaizam*

*Rozana*

*Nur Batrisyia*

## ACKNOWLEDGEMENT

In the name of Allah, the Most Gracious and the Most Merciful.

First of all, I wish to say that I am thankful to Allah for giving me the guidance, perseverance and strength during this challenging period and blessed me with the success of this Master of Science (Construction Management).

My word of thanks and special mention also goes to Prof. Dr. Muhd.Zaimi Abd Majid, whom, as thesis Supervisor, had given me whole-hearted support, professional advise, guidance and trustful ideas, I should say, is the person who is responsible for this achievement.

To all the Officials and Professional Heads at Opus (M) Bhd, Mr. Muhinder Singh, En. Mohd. Pauzi Ismail, En. Ramlan Haron, En. Suhaimi Aziz, En. Mohd Noor Saad, I too wish to extend my special thanks for the support and valuable information given.

Last, but not least, a big thank you to all the concerned parties or individuals who had contributed, in one way or another, directly or indirectly, towards the success of this project mine.

May Allah bless and bestow us all with good deeds, good health, love, kindness and success in life. Thank you.

## ABSTRACT

Currently, most of the slope failure occurred in highways due to inadequate design and lack of maintenance to address current situation. Slopes failures along the highways in Malaysia have been occurring and can be considered as an unpredictable event. One of the good examples is slope failure, which happened in 1996 at KM 303.80 (South Bound) near Gua Tempurung, Perak. The objective of this research is to identify the type of defects that contribute to the slope failure, identify and establish the common failures at various slope angle and to identify common type of slope repair in Malaysia.. Literature review and case study has conducted to achieve the objectives .Based on the case study that has been carried out, there are few types of defects that contribute to the slope failure such as water seepage and collapsed drain. In this case study, slope failures also occurred due to slope angles and height. Stone pitching and rockfill were identified is a common method type of slope repair in highway. A few recommendations need to be addressed by the designers or client when they intend to design a new slope along the highway such as type of vegetation, type of drain, accessibility, etc. In considering all these factors, it will benefit to the owner or client in term of maintenance cost in future. In conclusion, Asset Management has played an important role in future not only for slope along the highway but to other assets such as building, tower, etc. in order to maximize the company profit.

## ABSTRAK

Pada masa kini, kebanyakan kegagalan curun di sepanjang lebuhraya adalah kemungkinan disebabkan oleh rekabentuk yang tidak mencukupi dan kegagalan menjalankan kerja-kerja penyelenggaraan dengan baik berdasarkan kepada perkembangan dan keadaan semasa. Kegagalan curun di sepanjang lebuhraya di Malaysia sering terjadi dan kejadian ini adalah sukar dijangkakan. Contoh yang terbaik ialah kegagalan cerun yang berlaku di Gua Tempurung, Perak, pada tahun 1996 di KM 303.80 arah selatan. Tujuan kajian kes ini adalah untuk mengenal-pasti jenis-jenis kecacatan yang boleh membawa kepada kegagalan cerun, mengenal-pasti kegagalan cerun disebabkan oleh sudut dan ketinggian yang berbeza dan mengenal-pasti kaedah atau cara pembaikan cerun-cerun yang kebanyakannya digunakan di Malaysia. Kajian kes dijalankan terhadap data-data yang diperolehi dan juga melalui kajian literatur. Berdasarkan kepada kajian yang telah dijalankan, kecacatan yang sering menyebabkan kegagalan cerun adalah *water seepage* dan *collapsed drains*. Di samping itu juga, kegagalan cerun juga biasanya terjadai disebabkan oleh sudut cerun dan ketinggian yang berbeza. Kaedah *Stone pitching* dan *rock fill* adalah dua kaedah yang biasa dilakukan di dalam pembaikan cerun di lebuhraya, Malaysia. Beberapa cadangan telah diutarakan kepada jurutera rekabentuk dan pemilik diantaranya ialah mengambil kira jenis sistem perparitan yang digunakan, jenis tumbuhan atau pokok yang hendak ditanam dan kemudahan akses untuk melakukan kerja-kerja penyelenggaraan. Secara keseluruhannya, pengurusan aset pada masa depan adalah penting untuk memaksimumkan keuntungan.



**TABLE OF CONTENTS**

<b>CHAPTER</b>	<b>TITLE</b>	<b>PAGE</b>
	<b>DECLARATION</b>	<b>ii</b>
	<b>DEDICATION</b>	<b>iii</b>
	<b>ACKNOWLEDGMENT</b>	<b>iv</b>
	<b>ABSTRACT</b>	<b>v</b>
	<b>ABSTRAK</b>	<b>vi</b>
	<b>TABLE OF CONTENTS</b>	<b>vii</b>
	<b>LIST OF TABLES</b>	<b>x</b>
	<b>LIST OF FIGURES</b>	<b>xii</b>
	<b>LIST OF APPENDICES</b>	<b>xiv</b>
<b>1</b>	<b>INTRODUCTION</b>	<b>1</b>
	1.1 Introduction	1
	1.2 Background of Study	2
	1.3 Problems Statement	3
	1.4 Objective of Research	3
	1.5 Scopes of Research	4
	1.6 Research Methodology	4
<b>2</b>	<b>LITERATURE REVIEW</b>	<b>6</b>
	2.1 Introduction	6
	2.2 Definition of Asset Management	6

2.3	Definition of Maintenance	7
2.4	Asset Life Cycle	8
2.5	Design Consideration	9
2.5.1	Factor of Safety	9
2.5.2	Critical Potential Failure Paths	10
2.5.3	Representative Shear Strength	10
2.5.4	Ground Water Conditions	10
2.5.5	Effects of Erosion	11
2.5.6	Seismic Loading	11
2.5.7	Potential Blast Effects	12
2.6	Slopes as an Asset (Geotechnical assets)	12
2.6.1	Cut Slope	13
2.6.2	Embankment Slope	13
2.6.2.1	Elements of Slope	13
2.7	Slope Conditions Assessment	14
2.7.1	Aerial View Inspection	15
2.7.2	Visual on Foot Inspection	16
2.7.2.1	Periodical Inspection	16
2.7.2.2	General Inspection	16
2.7.3	Routine Maintenance Inspection	17
2.7.4	Engineer Maintenance for Inspection	18
2.8	Type of Defects	20
2.9	Important of Surface Cover and Rainfall	20
2.10	Maintenance Aspects to be Considered during design stage	21
2.11	Slope Failures Categorization	22
2.11.1	Causes of Slope Failure	23
2.12	Type of Remedial Measures	25
2.12.1	Erosion	26
2.12.2	Other Measures	27
2.13	Rehabilitation Works Flow	28

<b>3</b>	<b>CASE STUDY</b>	<b>30</b>
	3.1 Introduction	30
	3.2 Case Study	30
	3.2.1 Area of Case Study	31
	3.3 Data Collected	33
	3.4 Site Inspection	33
	3.4.1 General Inspection	34
	3.4.2 Periodical Inspection	35
	3.5 Condition Rating	38
	3.5.1 Inspection Guidelines	38
	3.5.2 Reporting	42
	3.6 Defects Encountered During Inspections	42
<b>4</b>	<b>DATA ANALYSIS AND DISCUSSION</b>	<b>44</b>
	4.1 Introduction	44
	4.2 Data Analysis	44
	4.2.1 No of Inspected Slopes	45
	4.2.2 Type of Defects Encountered During Inspection at Section C1 (2005 – 2007)	47
	4.3 Failures at Various Angles of Slope	53
	4.4 Common Type of Slope Repairs	55
<b>5</b>	<b>CONCLUSION AND RECOMMENDATION</b>	
	5.1 Introduction	59
	5.2 Conclusion	59
	5.2 Recommendation	60
	<b>REFERENCES</b>	<b>61</b>
	<b>Appendices</b>	<b>63 - 112</b>

**LIST OF TABLES**

<b>TABLE NO.</b>	<b>TITLE</b>	<b>PAGE</b>
2.1	Slope Failure Triggering Mechanism (Abd. Rahman. F, 2007)	24
2.2	Percentage of Causes of Slope Failure (Abd. Rahman. F, 2007)	25
3.1	Overall Slope Conditon Criteria	37
3.2	Priority Rating	37
3.3	Rock Classifications	39
3.4	Slope Material Criteria	40
3.5	Geological Structure (Discontinuity)	40
3.6	Rock Mass Discontinuities	41
3.7	Condition of Vegetation Coverage	42
4.1	Total Number of Inspected Slope at Section C1	45

4.2	Type of Defects Encountered (2005 – 2007)	47
4.3	Failures at Various Angles of Slope	54
4.4	Common Type of Slope Repairs	56

**LIST OF FIGURES**

<b>FIGURE NO.</b>	<b>TITLE</b>	<b>PAGE</b>
1.1	Flow Chart of Research Methodology	5
2.1	Asset Life Cycle	8
2.2	Elements of Slope (Geo, 1995)	14
2.3	Type of Defects (PLUS Manual, 2000)	20
2.4	Slope Failures Categorization (Abd. Rahman. F, 2007)	23
2.5	Rehabilitation Works Flow (Abd. Rahman. F, 2007)	29
3.1	Map shows area of researched, Section C1 (Bidor to Ipoh Selatan)	32
3.2	Photos of Defect encountered during inspection	43
4.1	Graph shows the Total Number of Inspected Slopes at Section C1	46
4.2	Total Number. of Slopes with Defects (2005 – 2007)	48

4.3	Percentage (%) of Overall Slope with Defects	48
4.4	Percentage (%) of Slope with Defects (Slope Distress)	49
4.5	Percentage (%) of Overall Slope with Defects (Drainage Condition)	50
4.6	Percentage (%) of Overall Slope with Defects (Slope Surface Condition)	52
4.7	Percentage (%) of Failure at Various Angles of Slope	54
4.8	Percentage (%) of Common type of Slope Repairs	57
4.9	Common Type of Slope Repair	57

## LIST OF APPENDICES

APPENDIX	TITLE	PAGE
A/1	Slope ID	63
A/2	Slope ID, <i>cont'd</i>	64
A/3	Slope ID, <i>cont'd</i>	65
A/4	Slope ID, <i>cont'd</i>	66
A/5	Slope ID, <i>cont'd</i>	67
A/6	Slope ID, <i>cont'd</i>	68
A/7	Slope ID, <i>cont'd</i>	69
A/8	Slope ID, <i>cont'd</i>	70
A/9	Slope ID	71
B/1	Defects Encountered (2005-2007)	72
B/2	Defects Encountered (2005-2007), <i>cont'd</i>	73



B/3	Defects Encountered (2005-2007), <i>cont'd</i>	74
B/4	Defects Encountered (2005-2007), <i>cont'd</i>	75
B/5	Defects Encountered (2005-2007), <i>cont'd</i>	76
B/6	Defects Encountered (2005-2007), <i>cont'd</i>	77
B/7	Defects Encountered (2005-2007), <i>cont'd</i>	78
B/8	Defects Encountered (2005-2007), <i>cont'd</i>	79
B/9	Defects Encountered (2005-2007), <i>cont'd</i>	80
B/10	Defects Encountered (2005-2007)	81
C/1	Summary of Slope Periodical Inspection	82
C/2	Summary of Slope Periodical Inspection, <i>cont'd</i>	83
C/3	Summary of Slope Periodical Inspection, <i>cont'd</i>	84
C/4	Summary of Slope Periodical Inspection, <i>cont'd</i>	85
C/5	Summary of Slope Periodical Inspection, <i>cont'd</i>	86
C/6	Summary of Slope Periodical Inspection, <i>cont'd</i>	87
C/7	Summary of Slope Periodical Inspection, <i>cont'd</i>	88
C/8	Summary of Slope Periodical Inspection, <i>cont'd</i>	89

C/9	Summary of Slope Periodical Inspection, <i>cont'd</i>	90
C/10	Summary of Slope Periodical Inspection, <i>cont'd</i>	91
C/11	Summary of Slope Periodical Inspection, <i>cont'd</i>	92
C/12	Summary of Slope Periodical Inspection, <i>cont'd</i>	93
C/13	Summary of Slope Periodical Inspection, <i>cont'd</i>	94
C/14	Summary of Slope Periodical Inspection, <i>cont'd</i>	95
C/15	Summary of Slope Periodical Inspection, <i>cont'd</i>	96
C/16	Summary of Slope Periodical Inspection, <i>cont'd</i>	97
C/17	Summary of Slope Periodical Inspection, <i>cont'd</i>	98
C/18	Summary of Slope Periodical Inspection, <i>cont'd</i>	99
C/19	Summary of Slope Periodical Inspection, <i>cont'd</i>	100
C/20	Summary of Slope Periodical Inspection	101
D/1	Rainfall Data	102
D/2	Rainfall Data, <i>cont'd</i>	103
D/3	Rainfall Data, <i>cont'd</i>	104
D/4	Rainfall Data, <i>cont'd</i>	105

D/5	Rainfall Data, <i>cont'd</i>	106
D/6	Rainfall Data	107
E/1	Work Orders at Section C1 (Bidor to Ipoh Selatan)	108
E/2	Work Orders at Section C1 (Bidor to Ipoh Selatan)	109
F/1	Periodical Inspection Form	110
F/2	Periodical Inspection Form	111
G	Typical of Slope	112

## **CHAPTER 1**

### **INTRODUCTION**

#### **1.1 Introduction**

It has been long recognized that those who design slopes have been given inadequate consideration to the maintenance problems that are related to many designs. Many of new design, maintenance aspects are not taking into account due to cost saving and time constraint approaches only. In order to overcome this problem, the understanding of asset life-cycle process, consisting of asset development and asset management is necessary especially in developing country such as Malaysia.

Designing new assets such as slopes, highways, bridges, culverts, etc, need a proper planning, accurate information based on experiences and good coordination between owner, consultant, asset manager and contractor. On the other hand, concept of concurrent engineering should be implemented between all party involved.

## 1.2 Background of Study

Currently, maintenance considerations in slope design by consultants or engineers are not taking into account due to cost saving and time constraint. There are few factors that need to be considered during design stage by all parties such as factor of safety, critical potential failure paths, representative shear strength, ground water conditions and effects of erosion (Potter. T, 2000).

Cut slope can be described as a natural material whereby the soil is not homogeneous. It has been constructed according to the required angle and height. Embankment slope is a man made slope whereby the materials should be more or less homogenous (Gue, 1995).

Slope condition assessment is required before any remedial works carried out by the contractor. Inspection and monitoring are the important aspects when carrying out slope condition assessment. There are some methods involved during slope condition assessment. One of the methods is to conduct aerial view inspection. Periodical inspection and general inspection are required in order to identify the maintenance needs of the slope. All inspections were conducted by maintenance engineer and inspectors (PLUS Manual, 2000).

Slope protection or types of slope repairs also play an important role in order to reduce slope deterioration and slope failure along the highways. Understanding of suitable method of slope repair is necessary for engineers. Beside of that the type of vegetation used in slope will also to be considered based on their material characteristics and function (Abd. Rahman, 2007).

### **1.3 Problems Statement**

Slopes failures along the highways in Malaysia have been occurring and can be considered as an unpredictable event. One of the good examples is slope failure, which happened in 1996 at KM 303.80 (South Bound) near Gua Tempurung, Perak and Bukit Lanjan, KM 21.8 (East Bound) in November 2003 due to some unpredictable reasons such as high intensity of rainfall, improper drainage systems, third party activities, slope surface protection, etc. Most of the slope failure occurred in highways due to inadequate design and lack of maintenance to address current situation.

In current practice, the maintenance aspect has not been given a due consideration by the Authorities or Consultants in producing any new design. Maintenance consideration should begin at earlier stage, during the location studies and continue throughout the design process.

### **1.4 Objective of Research**

The aim of this research is to identify the elements or aspects of maintenance that need to be considered during the design stage for slope; To achieve this aim, the following objectives have been develops:

- a. To identify the type of defects that contribute to the slope failure;
- b. To identify the slope failures at various angles of slope; and

- c. To identify the common types of slope repair in Malaysia.

## **1.5 Scopes of Research**

The scope of this study will focus on information gathered through periodical and general inspections at Section C1, from KM 340.00 to KM275.00, North-South Expressway (Bidor to Ipoh Selatan) for three consecutive years (2005, 2006 and 2007).

Secondly, this research will also focus on defects observed during periodical and general inspections at Section C1, from KM 340.00 to KM275.00, North-South Expressway (Bidor to Ipoh Selatan) for three consecutive years (2005, 2006 and 2007).

## **1.6 Research Methodology**

The research methodology of this study involved literature review on journal, research papers, books, proceedings, etc. which were related to the research topic.

Case study was carried out on the slope or embankment along North-South Expressway (PLUS). Refer to the **Figure 1.1** below for the flow chart of the research methodology.




Figure 1.1: Flow Chart of Research Methodology